

**PUBLIC SAFETY NOTICE**

**Intertek Warns of Potential Safety-Related Issue with  
Bumper Impact Bars Bearing a CAPA Quality Seal**

Published: December 12, 2018

The following is a notification from Intertek that the *Hui Yih* bumper impact bars identified below bearing the CAPA Certification Mark (i.e., CAPA Quality Seal) have been determined to pose a potential safety hazard.

<b>Product Description</b>		Bar, Impact					
<b>Make</b>	<b>Model</b>	<b>Years</b>	<b>Details</b>	<b>AM Part Number</b>	<b>OEM Part Number</b>	<b>PartsLink Number</b>	<b>Country</b>
Ford	Fusion	2013-2016		FD54138AH	DG9Z17906A	FO1106365	US
<b>Manufacturer</b>		Hui Yih Industrial Co., Ltd.					
<b>Number of Units</b>		4,327					
<b>Lot Numbers</b>		04/17A, 07/17A, 11/17A, 12/17A, 01/18A, 03/18A, 04/18A, 04/18B, 06/18A, 08/18A, 09/18A, 09/18B					
<b>Potential Hazard</b>		The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.					
<b>Sold By</b>		Distributors of aftermarket parts.					
<b>What To Do</b>		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Hui Yih directly.					