

PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Reinforcement Bar Bearing a CAPA Quality Seal

Published: April 20, 2022

The following is a notification from Intertek that the Auto Power Reinforcement Bar identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Bar, Reinforcement					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Toyota	Corolla	2017	50 th Anniversary Special Edition	TYR2571-1A	5202102240	TO1006249	US
Toyota	Corolla	2017-2019	CE/L/LE/LE ECO/XLE	TYR2571-1A	5202102240	TO1006249	US
Toyota	Corolla	2017-2019	SE/XSE	TYR2571-1A	5202102240	TO1006249	US
Manufacturer		Auto Power Enterprise Co., Ltd.					
Number of Units		245					
Lot Numbers		10/20A					
Potential Hazard		The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.					
Sold By		Distributors of aftermarket parts					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Auto Power directly.					