



PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Left Headlamp Assembly Bearing a CAPA Quality Seal

Published: May 31, 2024

The following is a notification from Intertek that the TYC headlamp identified below bearing the CAPA certification mark (CAPA Quality Seal) has been determined to pose a potential safety hazard.

| | | | | | | | |
|----------------------------|--------------|--|----------------|-----------------------|------------------------|-------------------------|----------------|
| Product Description | | Headlamp Assembly, L | | | | | |
| Make | Model | Years | Details | AM Part Number | OEM Part Number | PartsLink Number | Country |
| Jeep | Compass | 17-21 | | 20-9982-00-9 | 5512707AF | CH2503295 | US |
| Manufacturer | | TYC Brother Industrial Co., Ltd. | | | | | |
| Number of Units | | 7,017 | | | | | |
| Lot Numbers | | 04272010, 10052010, 11162010, 12142010, 02082110, 03152110, 03222110, 04122110, 05032110, 08022110, 09132110, 10042110, 10112110, 01032210, 02282210, 03142210, 04182210, 05022210, 05232210, 06202210, 07042210, 07252210, 08082210, 08152210, 08292210, 09122210, 10102210, 10242210, 10312210, 11072210, 11212210, 11282210, 01092310, 01162310, 01302310, 02062310, 02132310, 02202310, 03062310, 03132310, 04102310, 07032310, 09252310 | | | | | |
| Potential Hazard | | The low beam function may become inoperable. If this were to occur, driver and oncoming traffic visibility would be impaired. To date, 2 complaints have been received. | | | | | |
| Sold By | | Distributors of aftermarket parts | | | | | |
| What To Do | | Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact TYC directly. | | | | | |