



PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Hoods Bearing a CAPA Quality Seal

Published: October 04, 2024

The following is a notification from Intertek that the Hui Yih hoods identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Hood					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Subaru	Ascent	2019-2021		SB21195LAH	57229XC00A9P	SU1230155	US
Manufacturer		Hui Yih Industrial Co., Ltd.					
Number of Units		107					
Lot Numbers		04/23A					
Potential Hazard		<p>The striker and hinge mounting weldments may not function properly as intended. CAPA identified poor quality spot welds that do not meet CAPA standards.</p> <p>To date, 2 complaints have been reported</p>					
Sold By		Distributors of aftermarket parts					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Hui Yih directly.					