

PUBLIC SAFETY NOTICE

**Intertek Warns of Potential Safety-Related Issue with
Bumper Beam Bearing a CAPA Quality Seal**

Published: April 20, 2022

The following is a notification from Intertek that the Auto Power Bumper Beam identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Beam, Bumper					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Dodge	Ram Pick-Up	2013-2019	1 piece – w/Ram logo on grille	DGR3430A	68196999AB	CH1006232	US
Manufacturer		Auto Power Enterprise Co., Ltd.					
Number of Units		476					
Lot Numbers		06/21A					
Potential Hazard		The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.					
Sold By		Distributors of aftermarket parts					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Auto Power directly.					